

MOULDED PARTS & SHAPES

Moulded Parts Selection Guide

Part Number	Part Description	As Supplied	After Recovery
301A011 Series	T transition		
322A112 Series	90° side, breakout transition		
342A012 Series	45° side, breakout transition		
342A112 Series	45° side, breakout transition		
362A014 Series	30° side, breakout transition		
382A012 Series	Y transition		
462A011 Series	1 into 3 cable transition		
562A011 Series	1 into 4 cable transition		

5

Note: For further information on the extensive range of moulded parts and shapes available, or for assistance with your specific requirements, please contact us. For further information on the range of heat guns and adhesives available for installing moulded parts and shapes, please refer to the **Application Equipment** and **Tapes & Adhesives** sections in this catalogue. Moulded parts and shapes material performance characteristics can be found at the end of this section.