

## MOULDED PARTS & SHAPES

### Moulded Parts & Shapes

#### Part Numbering Guide

**Ordering Example: 202K132-25-01/86-0**

**Number of Openings:**

2 = 2 openings (Boots) 2  
3 = 3 openings (Transitions)  
4 = 4 openings (Transitions)

**Angle of Part:**

*All openings circular boots*  
0 = 0° (straight) 4 = 45° 20  
2 = 90° 6 = 30°

One opening for non-circular boots

0 = 0° (straight) 5 = 45°  
3 = 90° 7 = 30°

**Part Type:**

A = Non lipped K = Lipped 202K  
C = Lipped S = Screened  
D = Lipped W = Feedthrough

**Family Member:** 202K1

5

**Part Size:**

11 = Smallest 202K132  
*through to the*  
99 = Largest

**Material:**

-3 = Semi-rigid Polyolefin  
-4 = Flexible Polyolefin 202K132-25  
-12 = Fluoro-elastomer  
-25 = Fluid resistant elastomer  
-100 = Low fire hazard

**Modification (Optional):** 202K132-25-01

00 = Potting ports 11 = One lip removed with potting ports  
01 = One lip removed 21 = Two lips removed with potting ports  
02 = Two lips removed G (mods) = Special constructions

**Adhesive (Optional):**

/42 = General purpose hot melt adhesive  
/86 = High performance hot melt adhesive 202K132-25-01/86  
/180 = Low fire hazard hot melt adhesive  
/225 = Pre-coated curing adhesive

**Part Colour:**

0 = Black 202K132-25-01/86-0

**Note:** For further information on the adhesives available please refer to the **Tapes & Adhesives** section of this catalogue. For further information on the extensive range of moulded parts and shapes available, or assistance with your specific requirements, please contact us.